10/719, 222.

UEC 1 8 2006

LEWLETT-PACKARD CO.

PATENT APPLICATION

regal Dept., Intellectual Property Section 3404 E. Harmony Road, M/S 79
Fort Collins, Colorado 80528

ATTORNEY DOCKET NO. 200313046-1

THE REPORT OF THE PARTY OF THE

December 13, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Re: United States Patent No. 7,046,415 issued May 16, 2006

for MICRO-MIRRORS WITH FLEXURE SPRINGS

Dear Sir:

Enclosed for filing (in duplicate) is a Certificate of Correction of the above-identified patent. Please record the document.

It is believed that no fees should be necessary since the error is a Patent Office typographical error. However, should any fees be necessary, please charge Deposit Account No. 08-2025.

Sincerely,

KLAAS, LAW, O'MEARA & MALKIN, P.C.

JKM/jlr Enclosures Certificate

of Correction

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO

: 7,046,415

DATED

: May 16, 2006

INVENTOR(S): Jilani et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims

Col. 8 (line 17), delete "compnses:" and insert therefor --comprises:--.

MAILING ADDRESS OF SENDER: Hewlett-Packard Company Intellectual Property Section 3404 E. Harmony Road, M/S 79 Fort Collins, CO 80528

7,046,415 PATENT NO. _

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

HEWLETT-PACKARD CO. Legal Dept., Intellectual Property Section 3404 E. Harmony Road, M/S 79 Fort Collins, Colorado 80528

PATENT APPLICATION

ATTORNEY DOCKET NO. 200313046-1



December 13, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

United States Patent No. 7,046,415 issued May 16, 2006

for MICRO-MIRRORS WITH FLEXURE SPRINGS

Dear Sir:

Enclosed for filing (in duplicate) is a Certificate of Correction of the above-identified patent. Please record the document.

It is believed that no fees should be necessary since the error is a Patent Office typographical error. However, should any fees be necessary, please charge Deposit Account No. 08-2025. A duplicate copy of this letter is enclosed for that purpose.

Malkin

Sincerely,

KLAAS, LAW, O'MEARA & MALKIN, P.C.

JKM/jlr Enclosures U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO

: 7,046,415

DATED

: May 16, 2006

INVENTOR(S): Jilani et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims

Col. 8 (line 17), delete "compnses:" and insert therefor --comprises:--.

MAILING ADDRESS OF SENDER: Hewlett-Packard Company Intellectual Property Section 3404 E. Harmony Road, M/S 79 Fort Collins, CO 80528

7,046,415 PATENT NO.

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.